
DEMARREUR SSANGYONG

Remanufactured

Core code : 11

FADADE

3599771048771



TECHNICAL DATA

Voltage [V]	**12 V**
Rated Power [kW]	**2.2 kW**
Number of mounting bores	**2**
Number of Teeth	**10**
Clamp	**Pin "30" M8 B+**
Clamp	**Pin "50" M6**
Rotation Direction	**Clockwise rotation**
Flange Diameter [mm]	**83 mm**
Number of threaded holes	**2**

PICTURES











Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

SSANGYONG		
ACTYON II - 2.0 XDi 4x4	150 ch	08.2012 >
ACTYON SPORTS Pick-up (QJ) - 2.0 Xdi	155 ch	09.2011 >
ACTYON SPORTS Pick-up (QJ) - 2.0 Xdi 4WD	155 ch	09.2011 >
ACTYON SPORTS II - 2.0 Xdi	155 ch	01.2012 >
KORANDO (CK) - 2.0 e-XDi	150 ch	02.2012 >
KORANDO (CK) - 2.0 e-XDi 4WD	150 ch	02.2012 >
KORANDO (CK) - 2.0 e-XDi	175 ch	11.2010 >
KORANDO (CK) - 2.0 e-XDi 4WD	175 ch	11.2010 >
REXTON W - 2.0 Xdi	155 ch	07.2012 > 11.2015
REXTON W - 2.0 Xdi Traction intégrale	155 ch	07.2012 > 11.2015
REXTON W - 2.2 Xdi	178 ch	07.2015 > 06.2017
REXTON W - 2.2 Xdi Traction intégrale	178 ch	07.2015 > 06.2017
REXTON W / REXTON VAN - e-XDi	178 ch	07.2015 >
REXTON W / REXTON VAN - e-XDi Traction intégrale	178 ch	07.2015 >
REXTON (Y400, Y450) - 2.2 Xdi	181 ch	07.2017 >
REXTON (Y400, Y450) - 2.2 Xdi Traction intégrale	181 ch	07.2017 >
REXTON VAN (Y400) - e-XDi	181 ch	07.2017 >
REXTON VAN (Y400) - e-XDi 4WD	181 ch	07.2017 >
MUSSO (QK) - 2.2 e-XDi	181 ch	01.2018 >
MUSSO (QK) - 2.2 e-XDi 4WD	181 ch	01.2018 >
RODIUS II - 2.0 Xdi	155 ch	07.2013 >
RODIUS II - 2.0 Xdi 4WD	155 ch	07.2013 >