POMP DIR LANCER 2.0DI-D

Remanufactured

Core code : 73

FCDADP

3599771945100



TECHNICAL DATA

Operating Mode	**hydraulic**
Belt Pulley Ø [mm]	**104 mm**
Pulleys	**with V-ribbed belt pulley**
Info complémentaire	**without suction pipe**
for steering manufacturer	**KAYABA**
Number of grooves	**6**
Overall Length [mm]	**111 mm**
Pressure Line Connection Thread Size	**Ø16mm Bride**
Backflow Connector Thread Size	**F16x150**
Position of the input pipe [clock]	**11 hours (clock hand)**
Pulley fitting	**Pressed on**

PICTURES











Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

MITSUBISHI		
LANCER (2008-) 3 volumes (CY/Z_A) - 2.0 DI-D	140 ch	01.2008 >
LANCER SPORTBACK (2008-) (CX_A) - 2.0 DI-D	140 ch	06.2008 >