POMP DIR HYUNDAI ACCENT

Remanufactured

Core code : 70

FCDADP

3599771866894



TECHNICAL DATA

Operating Mode	**hydraulic**
Belt Pulley Ø [mm]	**111 mm**
Pulleys	**with V-ribbed belt pulley**
Pulleys	**without belt pulley**
Info complémentaire	**without suction pipe**
for steering manufacturer	**KAYABA**
Number of grooves	**6**
Pressure Line Connection Thread Size	**Ø16mm**
Backflow Connector Thread Size	**F16x150**
Position of the input pipe [clock]	**3 hours (clock hand)**
Pulley fitting	**Screwed**
Number of rear fixation points	**1**

PICTURES











Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

CHEVROLET		
SPARK (M300) - 1.0 LPG	65 ch	07.2010 >
SPARK (M300) - 1.0	68 ch	03.2010 >
SPARK (M300) - 1.0 LPG	68 ch	03.2010 >
SPARK (M300) - 1.2	82 ch	03.2010 >
SPARK (M300) - 1.2 LPG	82 ch	03.2010 >

HYUNDAI		
ACCENT (00-05) 3 volumes (LC) - 1.5 CRDi	82 ch	01.2002 > 11.2005
ACCENT (00-05) (LC) - 1.5 CRDi	82 ch	04.2002 > 11.2005