POMP DIR OUTLANDER I 2.0

Remanufactured

Core code : 70

FCDADP

3599771437988



TECHNICAL DATA

Operating Mode	**hydraulic**
Belt Pulley Ø [mm]	**144 mm**
Pulleys	**with V-ribbed belt pulley**
Info complémentaire	**without suction pipe**
Supplementary Article/Info 2	**with sensor**
for steering manufacturer	**KAYABA**
Number of grooves	**5**
Rotation Direction	**Clockwise rotation**
Position of the input pipe [clock]	**3 hours (clock hand)**
Pulley fitting	**Pressed on**

PICTURES











Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

MITSUBISHI		
LANCER (03-07) 3 volumes (CS_A) - 2.0	135 ch	12.2003 > 12.2013
LANCER (03-07) Break (CS_W) - 2.0	135 ch	09.2003 > 12.2007
OUTLANDER (03-06) (CU_) - 2.0	136 ch	05.2003 > 10.2006
OUTLANDER (03-06) (CU_) - 2.0 4WD	136 ch	05.2003 > 10.2006
OUTLANDER (03-06) (CU_) - 2.0 Turbo 4WD	201 ch	04.2004 > 10.2006
OUTLANDER (03-06) (CU_) - 2.0 Turbo-R 4WD	241 ch	**05.2003 > 10.2006**