POMP DIR HYUNDIA ELANTRA

Remanufactured

Core code : 70

FCDADP

3599771165485



TECHNICAL DATA

Operating Mode	**hydraulic**
Belt Pulley Ø [mm]	**100 mm**
Pulleys	**with V-ribbed belt pulley**
Pulleys	**without belt pulley**
for steering manufacturer	**KAYABA**
Number of grooves	**3**
Overall Length [mm]	**88 mm**
Pressure Line Connection Thread Size	**Ø16mm**
Backflow Connector Thread Size	**F16x150**
Position of the input pipe [clock]	**12 hours (clock hand)**
Pulley fitting	**Screwed**

PICTURES











Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

HYUNDAI		
COUPE (GK) - 1.6 16V	105 ch	03.2002 > 08.2009
	107 ch	03.2002 > 08.2009
COUPE (GK) - 2.0	136 ch	08.2001 > 08.2009
	139 ch	03.2002 > 08.2009
COUPE (GK) - 2.0 GLS	143 ch	02.2003 > 08.2009
ELANTRA (00-06) 3 volumes (XD) - 1.8	132 ch	06.2000 > 07.2006
ELANTRA (00-06) 3 volumes (XD) - 2.0	139 ch	06.2000 > 07.2006
	141 ch	06.2000 > 07.2006
	143 ch	10.2003 > 07.2006
ELANTRA (00-06) (XD) - 1.8	132 ch	06.2000 > 07.2006
ELANTRA (00-06) (XD) - 2.0	139 ch	06.2000 > 07.2006
	141 ch	06.2000 > 07.2006
	143 ch	10.2003 > 07.2006
TIBURON Coupé - 2.0 CVVT	143 ch	10.2006 > 12.2008
TRAJET (FO) - 2.0	140 ch	01.2004 > 07.2008
TRAJET (FO) - 2.0 CRDi	113 ch	04.2001 > 07.2008
TRAJET (FO) - 2.0	136 ch	**02.2004 > 07.2008**